

## Osa – Replacing the Display Screen

Tools Required:

Torx T20 bit/key

5mm Allen Wrench


Step 1: Using a Torx T20, remove the 4 securing bolts for the front of the Osa main beam.



Step 2: Remove the front section of the main beam. Tip: Rest/Secure it on the front fender using a short strap or similar.



Step 3: Follow the cable from the back of the display to where it connects to the bike's main harness. Disconnect these two connections. Note: The 3<sup>rd</sup> connection is a data port that is unused during normal riding. No cause for concern!



Step 4: Take note of the handlebar position at this step, so you can be sure to re-install them in the same position. Using a 5mm Allen key, remove the four 5mm securing bolts on the upper stem. The display will then come completely off.



Step 6: Reverse the steps above for the installation of the new unit.

Complete! Of course, please do not hesitate to reach out to the service department with any questions or concerns about the process. We are happy to assist further in any capacity possible!