

Makka – Replacing the Display Screen

Tools Required:

- T45 Torx Bit/Key
- T20 Torx Bit/Key
- 5mm Allen Wrench

Step 1: Remove the four T45 bolts that secure the headlight bracket. If needed, it can be helpful to angle the headlight forward to get better access to the two upper bolts.



To angle the headlight, gently loosen the securing 5mm bolt until the headlight can be tilted forward.




Step 2: Remove the four 5mm bolts that secure the handlebars.



Step 3: Remove the two T20 bolts that secure the display to the handlebar stem.



Step 4: Follow the display cable and disconnect the main connection.



Step 5: Begin by plugging in the new display unit and reverse the steps above for re-install.

Step 6: Test for functionality! Be sure to use the new keys provided with the new display.

Complete!