

CAKE Osa – Replacing the Fuse

Tools Required:

- Torx T25 bit/driver

1. Remove the battery for 10-15 minutes before anything




2. Using a Torx T25 bit, remove the 4 securing bolts for the controller lid



3. Locate the fuse inside the controller box



4. Identify if the fuse is blown. Sometimes this can be hard visually. If you are unsure, a multimeter continuity test would tell us for sure.



5. If blown, replace with the same size and shaped fuse, available at any local auto parts store (CAKE Service can also send a replacement if needed). If not blown, please reach out to the service team for further instruction.

Please don't hesitate to reach out with any questions or concerns before/during/after the process!
Thank you!

CAKE Service Team